

Conveyor Lighting Stand Installation Instructions



Detailed list of accessories(1.5M Conveyor)






Item	P/N	Name	size	Quantity
1	SC4EDZ021	1.A4 Hard rubber sleeve	A4	1
2	SC4EDZ022	Energy saving lamp	1.2M	1
3	SC4EDZ023	intermediate bracket	1.2M	2
4	SC4EDZ024	Square light stand	1.2M	2
5	SC4EDZ025	M6x65 screws	M6x65	4
6	SC4EDZ066	M6x50 screws	M6x50	2
7 8 9 10	SC4EDZ027 SC4EDZ028 SC4EDZ029 SC4EDZ0030	M4x20 screws M4x10 screws Light Power wire Top bracket	M4x20 M4x10 1M 1.09M	4 2 2 1


Step 1: Install the bottom bracket



Step 2: Installing the intermediate bracket



3.1 Use two M6X50 screws on the top to mount a 1.09 m bracket.







3.3 Fix the lamp holder to the bracket with M4X10 screws




3.4 Light 110V power cable connection













Step 4 :power wire connection installation

4.1, originally with a light, the machine has a terminal inside, you can directly connect the lamp holder power








Step 4 :power wire connection installation

4.2, originally without a light, the new light stand, should be directly connected to the internal power supply terminal







Red wire to L, black wire to N



